

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type			
02	007	022	0000002054	Part list see table below	Connectors	GSP1



*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected					
GSP1.6101.1	GSP1.6201.1	GSP1.6501.1	GSP1.650E.1	GSP1.6711.1	GSP1.7101.1
GSP1.7101.2	GSP1.7201.1	GSP1.7401.1	GSP1.7500.1	GSP1.7501.1	GSP1.8100.1
GSP1.8101.1	GSP1.8101.2	GSP1.8103.1	GSP1.8105.1	GSP1.810C.1	GSP1.810E.1
GSP1.8110.1	GSP1.8111.1	GSP1.8113.1	GSP1.811E.1	GSP1.8200.1	GSP1.8201.1
GSP1.8203.1	GSP1.8207.1	GSP1.820C.1	GSP1.8211.1	GSP1.8401.1	GSP1.8405.1
GSP1.8411.1	GSP1.8413.1	GSP1.8500.1	GSP1.8501.1	GSP1.850E.1	GSP1.8601.1
GSP1.8613.1	GSP1.8701.1	GSP1.8703.1	GSP1.8705.1	GSP1.870C.1	GSP1.870E.1
GSP1.9100.1	GSP1.9101.1	GSP1.9103.1	GSP1.910C.1	GSP1.910E.1	GSP1.9110.1
GSP1.9111.1	GSP1.9113.1	GSP1.911E.1	GSP1.9200.1	GSP1.9201.1	GSP1.920E.1
GSP1.9203.1	GSP1.9210.1	GSP1.9213.1	GSP1.9401.1	GSP1.9403.1	GSP1.9413.1
GSP1.941E.1	GSP1.9500.1	GSP1.9503.1	GSP1.8101.115	GSP1.8103.121	GSP1.870E.101
GSP1.9103.1M	GSP1.8101.121	GSP1.8201.121	GSP1.9103.121	GSP1.9203.121	3-108-148
3-108-414					

2 Type of change

V-Lock cord retaining feature as standard.

3 Detailed description of change

Old product appearance	New product appearance with V-Lock notch
	

Tooling was updated to include the V-Lock cord retaining feature for all affected part numbers.

4 Reason of change

Change of the tooling to improve the quality of the optionally available V-Lock notch and to implement it as a standard feature for the product GSP1.

5 Release date

The change will be rolled-out starting ww 12/2019 (Date code 1912 or higher on label) and lasts approx. 6 months depending on the variant. The validity of the approval certificate is not affected by this change.

Product Change Notification					PCN GSP1 New with V-Lock Notch		
owner	creation date	release date	released by	change order no	rev	page	D10-032-636
hollenpe	10.12.2018	14.03.2019	limachcl	2014647	A	1 of 2	

6 Impact of change and recommended action

Form	Yes	New form is fully backwards compatible
Fit	No	-
Function	Yes	V-Lock feature is standard (not an option anymore)
Production Site	No	-
Product Label	No	-
Customer Action	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
GSP1 Data Sheet	Data Sheet of the affected product
VAC13KS Data Sheet	Data Sheet of V-Lock Cord Sets

Product Change Notification					PCN GSP1 New with V-Lock Notch		
owner	creation date	release date	released by	change order no	rev	page	D10-032-636
hollenpe	10.12.2018	14.03.2019	limachcl	2014647	A	2 of 2	