

1 Products affected

SBU	PG	PGU	Type	Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.
02	006	016		0000001509	4301.XXXX.XX		KFA	
02	006	016		0000001533	KMFX.XXXX.XX		KMF	
02	006	016		0000001503	5110.XXXX.XX		5110	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)


2 Type of change

Modification of Approval marks new with CCC


3 Detailed description of change

Old Labels :


KMF






KFA



5110



NEW Labels :



All packing labels are new with approval marks.

KMF; KFA; 5110					0118.2086	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
31.01.2012 13:38:00	ros	31.01.2012	ros	23016	-	1 von 2

4 Reason of change

Chinese approval CCC

5 Released date

Release for series production

Ww03/2012

6 Impact of change and recommended action

Form: N/A
Fit: N/A
Function: N/A
Production Site: N/A
Product label: New with CCC aprobation

7 Reference Documents / Attachments

Kind of document	Document number	Remarks

KMF; KFA; 5110					0118.2086	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
31.01.2012 13:38:00	ros	31.01.2012	ros	23016	-	2 von 2